


69

Sno - 549/69



"स्वच्छ भारत अभियान"

DISTRICT: Khordha BLOCK: Tangi VILLAGE: Mahulhara
SCHOOL NAME: MAHULHARA P.G. SCHOOL CODE: 1009001
NO. OF STUDENT: 26 GIRLS: 12 BOYS: 14
STATUS OF TOILET: EXISTING: ✓ NOT EXISTING: ✗
TOILET REQUIREMENT: GIRLS: BOYS:
IF EXISTING: urinals usable (B, G)
but 2 WCs completely damaged

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	2 nos.
2	URINALS		-
3	DOORS(SIZE)		✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER: BORE WELL WITH PUMP: ✗ HAND PUMP: 01
WATER TANK: GROUND: ✗ OVERHEAD: ✗ (not functional in summers)

WATER TANK CAPACITY:
Remarks if any: - no electricity supply
- only source of water (1 hand pump)

B SETHI
29.1.15
Sign of School Head Master

ममता बाहु
Sign of School Mgt Committee

Swagat Das
29/01/15
Sign of Surveyor
MT (EM)

NAME: BHACI BATHI
SETHI
(M) 9178043827

NAME: MAMATA BAHU

NAME: SWAGAT DAS