


37



Sno - 539 / 37

"स्वच्छ भारत अभियान"

DISTRICT: Khordha BLOCK: Tangi

VILLAGE: Gedei Bwain Palna

SCHOOL NAME: PATNA CPS

SCHOOL CODE: 1006801

NO. OF STUDENT: 131 GIRLS: 78

BOYS: 53

STATUS OF TOILET: EXISTING: X

NOT EXISTING: ✓

TOILET REQUIREMENT: GIRLS: 02

BOYS: 02

IF EXISTING:

Total infra struct damaged (due to the missing boundary)

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: X

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any: - no electricity  
- only source of water = 1 well within the premises

P. Naik  
Sign of School Head Master

Sign of School Mgt Committee  
No SMC

Swagat Das  
Sign of Surveyor 27/1/15  
MT(Enw)

NAME: PRATIMA NAIK

NAME: B. Das  
27.1.15

NAME: SWAGAT DAS

1 8596021934

Headmaster  
Patna Primary School  
P.O:-Bhusandpur  
Block:-Tangi, Dist:-Khordha

C.R.C.C.  
S.T.U. Academy U.P. Kantalbai

27/1/15  
PMU  
(888 Karmach)