

52

Eno - 529 / 52



स्वच्छ भारत अभियान

DISTRICT: Khordha BLOCK: Tangi VILLAGE: Bhabara
 SCHOOL NAME: RAMACHANDI MES SCHOOL CODE: 1001802
 NO. OF STUDENT: 43 GIRLS: 22 BOYS: 21
 STATUS OF TOILET: EXISTING: totally damaged NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: BOYS:
 IF EXISTING: present toilet infrastru totally damaged in the cyclone (not in usable condition)

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	1
2	URINALS		2
3	DOORS(SIZE)		✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		✓

SOURCE OF WATER: BORE WELL WITH PUMP: X HAND PUMP: 1 no.
 WATER TANK: GROUND: X OVERHEAD: X
 WATER TANK CAPACITY:

Remarks If any: - no electricity supply
- only source of water (1 hand pump)

[Signature]
 Sign of School Head Master
28.1.2015

[Signature]
 Chair Person, S.M.C.
 Sign of School Mgt. Committee
 Ramachandi M.H. School
 Bhabara

[Signature]
 Swagat Das
28/01/15
 Sign of Surveyor
 MT (EM)

NAME: Panchanan Mohan
9937253245
 Headmaster

NAME: JHUNA PRADHAN

NAME: SWAGAT DAS

Ramachandi M.H. School
 Bhabara

[Signature]
 28/01/15
 (SSS Bhabara)