

39



Eno - 564 / 39

"स्वच्छ भारत अभियान"

DISTRICT: Khordha BLOCK: Tangi VILLAGE: Rasulpur
 SCHOOL NAME: RASULPUR P.S. SCHOOL CODE: 1007001
 NO. OF STUDENT: 65 GIRLS: 34 BOYS: 31
 STATUS OF TOILET: EXISTING: NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: BOYS:
 IF EXISTING: Boys (1 WC, 1 urinal)
Girls (1 WC, 1 urinal)

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2	} no persisting problems for toilet with only deficiency in water supply
2	URINALS	2	
3	DOORS(SIZE)	✓	
4	FLOOR LEVEL	✓	
5	WALL LEVEL	✓	
6	INTERNAL PLASTER	✓	
7	OUTER PLASTER	✓	
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK	✓	

SOURCE OF WATER: BORE WELL WITH PUMP: HAND PUMP: 01
 WATER TANK: GROUND: OVERHEAD:

WATER TANK CAPACITY:
 Remarks If any: - wiring available, but no electricity yet
- only source of water (1 handpump)

[Signature]
 Sign of School Head Master

[Signature]
 Sign of School Mgt Committee

[Signature]
 Sign of Surveyor
 MT (Eno)

NAME: LALITNARAYAN MOHAPATRA
7896 32 3225

NAME: PARVATI SAHU
(member), B.M.C

NAME: SWAGAT DAS
[Signature]
 (Eno)

Headmaster
Rasulpur Primary School