

44



Sno - 566/44

"स्वच्छ भारत अभियान"

DISTRICT: Khordha BLOCK: Tangi
SCHOOL NAME: RATANPUR PATNA P.S.
NO. OF STUDENT: 67 GIRLS: 33
STATUS OF TOILET: EXISTING: ✓
TOILET REQUIREMENT: GIRLS:
IF EXISTING: only 2 WCs for girls

VILLAGE: Ratnapurpatna
SCHOOL CODE: 1021001
BOYS: 34
NOT EXISTING:
BOYS:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2 (only for girls)	1 (girls)
2	URINALS	/	2 (boys)
3	DOORS(SIZE)		✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		✓

SOURCE OF WATER: BORE WELL WITH PUMP: X

HAND PUMP: 1 (dysfunctional messy)
OVERHEAD: ✓

WATER TANK: GROUND: X

WATER TANK CAPACITY:

Remarks if any: - no electricity supply
- only source of water (1 handpump)

S. Jai 27.01.15
Sign of School Head Master

Pratima Patra
Sign of School Mgt Committee

Swagat Das 27/1/15
Sign of Surveyor
MT(EM)

NAME: SAUDAMINI DEI
(M) 9338647469

NAME: PRATIMA PATRA

NAME: SWAGAT DAS

Headmaster
Ratanpurpatna Pry. School

27/1/15
CANCY
(888 Kancha)