(54)

Sno - (574) /54

"स्वच्छ भारत अभियान"

DISTRICT: Khordha BLOCK: Tangi VILLAGE: Taladiha

SCHOOL NAME: TALADIHA P-S SCHOOL CODE: 1017501

NO. OF STUDENT: 100 GIRLS: 59 BOYS: 41

STATUS OF TOILET: EXISTING: requires urgent repair (damaged) NOT EXISTING: X

TOILET REQUIREMENT: GIRLS: BOYS:

If EXISTING: no boundary wall makes the maintenance problematic

Sl.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		2 nos.
2	URINALS		2 nos.
3	DOORS(SIZE)		✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		✓

in bad condition requires urgent repair

SOURCE OF WATER: BORE WELL WITH PUMP: X HAND PUMP: 01 (showing) 01 (dysfunct)

WATER TANK: GROUND: X OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any: - no electricity supply
- only source of water (1 handpump is property of the village)

Sign of School Head Master 28/1/15 Sign of School Mgt Committee Sign of Surveyor Swagat Das 28/01/15 MT(Env)

NAME: PRASANNA KUMAR SRICHANDAN — 9938341299 NAME: APANNA DEI (member), SMC NAME: SWAGAT DAS

Headmaster
Taladiha Primary School
At-Taladiha, Po-Kulusai Dist-Khordha

28/1/15 CWCL (SS Panda)