

47



Eno - 579/47

"स्वच्छ भारत अभियान"

DISTRICT: Khurdha BLOCK: Tangi VILLAGE: Tangi
 SCHOOL NAME: TANGI P.G. SCHOOL CODE: 1021307
 NO. OF STUDENT: 183 GIRLS: 93 BOYS: 90
 STATUS OF TOILET: EXISTING: NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: BOYS:
 IF EXISTING: only 1 (for disabled) - newly constructed
2 damages WCs and urinals

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 no.	2 nos
2	URINALS	1 no.	2 nos
3	DOORS(SIZE)	/	✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		✓

SOURCE OF WATER: BORE WELL WITH PUMP: HAND PUMP:
 WATER TANK: GROUND: OVERHEAD:
 WATER TANK CAPACITY:

Remarks If any: - electricity available
 - only source of water (hand pump + well)

Mohanty 27.01.15
 Sign of School Head Master

Sign of School Mgt Committee

Swagat Das
 Sign of Surveyor 27/01/15

NAME: CHAPALAMOHANTY
 9238204867
 Headmaster
 Tangi Primary School, Khurdha

NAME:

not available

NAME: SWAGAT DAS

Balaram Behara
 C.R.C.
 S. G. Bidya Pitta
 Sanakusumi

27/1/15
 (SNC)
 (K. S. Panda)