

33

Sno - 557 / 33

"स्वच्छ भारत अभियान"

DISTRICT: Khurdha      BLOCK: Tangi      VILLAGE: Nuagarh  
 SCHOOL NAME: UGRATARA UPS      SCHOOL CODE: 101301  
 NO. OF STUDENT: 196      GIRLS: 104      BOYS: 92  
 STATUS OF TOILET:      EXISTING:       NOT EXISTING:   
 TOILET REQUIREMENT:      GIRLS: 02      BOYS: 02

IF EXISTING:  no winds  
 only 2 wcs (out of which 1 is completely damaged)

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	01	01
2	URINALS	/	
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		X
9	LEASE PIT/ SEPTIC TANK	01	—

SOURCE OF WATER:      BORE WELL WITH PUMP:       HAND PUMP: 02  
 WATER TANK:      GROUND:       OVERHEAD: 01 (dysfunctional)  
 WATER TANK CAPACITY: 300 ltr      (not used)

Remarks If any: - no electricity  
 - only source of water (1 well on shared basis)

Hm Rabindranath Balarsingh      ଶ୍ରୀମତୀ ରଞ୍ଜନା  
 Sign of School Head Master      Sign of School Mgt Committee  
27-01-2015

Swagat Das  
 Sign of Surveyor      27/01/15  
 MT (EW)  
 NAME: SWAGAT DAS

NAME: RABINDRANATH BALARSINGH      NAME: RANJANA CHAMPATI  
9556522847      (member), SMC  
 Headmaster

27/01/15  
 (888 Danda)