

1713

District Bolangir Block BHESASH Village Gambhazimal
 School Name Gambhazimal P.S School Code 713 21241308801
 No. of Student 39 Girls 21 Boys 18
 Status of toilet Existing Not Existing
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	X	2
2	Urinals	X	2
3	Doors (size)	0.62 X 1.86 X 3	2
4	Floor level	1-P.S	<input checked="" type="checkbox"/>
5	Wall level	B/W	<input checked="" type="checkbox"/>
6	Internal plaster	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	Outer plaster	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	Inspection Chamber	X	<input checked="" type="checkbox"/>
9	Lease pit / septic tank	X	<input checked="" type="checkbox"/>

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity
 Electricity - Available / Not available.

Remarks if any: Existing toilet in damage.
Stamp No - Available.

Gopal Behara
H M Gambhazimal
 Sign of School head master

Sarada Ch Behara
 Sign of School Mgt Committee

8/12/15
 Sign of Surveyor

Name

Name

Name

Sumantra Kumar
patel

8/12/15