

1748

District Bolansar Block Dittasari Village Gudguda
 School Name Gudguda Govt P.S. School Code 1748 21241311801
 No. of Student 45 Girls 22 Boys 23
 Status of toilet Existing Not Existing
 Toilet Requirement Girls Boys
 If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
2	Urinals	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	Doors (size)	<u>0.58 X 1.78 X 3</u>	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
4	Floor level	<u>1.P.S</u>	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
5	Wall level	<u>B/W</u>	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
6	Internal plaster	<u>4</u>	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
7	Outer plaster	<u>4</u>	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
8	Inspection Chamber	<u>X</u>	<input checked="" type="checkbox"/>
9	Lease pit / septic tank	<u>X</u>	<input checked="" type="checkbox"/>

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity
 Electricity - Available / Not available.

Remarks if any: Boys toilet in damage & a NO-girls toilet.

Sign of School head master
[Signature]
Headmaster
 Name **Govt. Primary School**
Gudguda

Sign of School Mgt Committee
[Signature]
 Name

[Signature]
 Sign of Surveyor
 Name Sumanta Kumar Patel

[Signature]
08/11/15