

District Bolangan Block Pittabath Village Nuarpada
 School Name Nuarpada Govt P.S School Code ~~117~~ 21241301003
 No. of Student 43 Girls- ~~20~~ 23 Boys- 20
 Status of toilet Existing Not Existing
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1	<input checked="" type="checkbox"/>
2	Urinals	X	1
3	Doors (size)	0.64x1.50	<input checked="" type="checkbox"/>
4	Floor level	1.P.S	<input checked="" type="checkbox"/>
5	Wall level	B/W	<input checked="" type="checkbox"/>
6	Internal plaster	yes X	<input checked="" type="checkbox"/>
7	Outer plaster	yes X	<input checked="" type="checkbox"/>
8	Inspection Chamber	yes X	<input checked="" type="checkbox"/>
9	Lease pit / septic tank	yes X	<input checked="" type="checkbox"/>

Source of Water NO Bore well with pump / Hand pump
 Water tank X Ground / Overhead
 Water tank Capacity X
 Electricity - Available / Not available.

Remarks if any: Toilet in Damaged condition.

Beena Sahu
 incheran
 Sign of School head master

G. S. S. S.
 Sign of School Mgt Committee
 no present
 Absent

[Signature]
 Sign of Surveyor

Name

Name

Name Sunmanta Kumar
Patel

[Signature]
08/11/15